

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|------------------------|--------------------------------|---------------------------------|------------------------|
| Intersection ID: 17561 | Main Street: BRIGHTON_BROOK_DR | Cross Street: BROOK_CROSSING_CT | Location: E |
| ADA ID: 34A57EF64D36 | Ramp Type: BlendTrans2 | Initial Pass/Fail: Pass | Overall Compliance: No |
| | | Severity Score: 2.5 | |

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

CURB GAP 1.0

PROW/ADA:

Not Found, R305.1.4, R305.2

Total Cost: \$ 3200.00

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|-------|------------|-----------------------------|-------|
| N/A | Ramp Length (in) | 104.0 | Yes | BlendTrans Slope (%) | 3.2 |
| Yes | Ramp Width (in) | 99.0 | Yes | BlendTrans XSlope (%) | 1.9 |
| N/A | Flare Type LT | None | N/A | Flare Type RT | None |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | Yes | DWS Provided? | Yes |
| N/A | Landing Width (in) | N/A | Yes | DWS Contrast? | Yes |
| N/A | Landing Slope (%) | N/A | Yes | DWS Length (in) | 24.0 |
| N/A | Landing X Slope (%) | N/A | No | DWS Full Width? | No |
| N/A | Landing Curb? (Y/N) | No | No | DWS Offset (in) | 3.0 |
| N/A | Shared Landing? | No | | | |
| Yes | Gutter Ponding? | No | Yes | Gutter Slope (%) | 2.1 |
| Yes | Gutter Lip Ht (in) | 0.0 | Yes | Gutter X Slope (%) | 2.0 |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | X Walk 1 Direction | To NW | | X Walk 2 Direction | To SW |
| | X Walk 1 Width (in) | N/A | | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 3.0 | | X Walk 2 Slope (%) | 0.2 |
| | X Walk 1 X Slope (%) | 0.2 | | X Walk 2 X Slope (%) | 4.3 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 1.6 | | Clear Space? | Yes |
| | Road X Slope (%) | 2.3 | N/A | Clear Space to XWalk (in) | N/A |
| Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | | | No | Curb Slope (%) | 8.9 |

Street 1 Name BRIGHTON BROOK DR

Stop Condition-Street 1 None

Street 2 Name BROOK CROSSING CT

Stop Condition-Street 2 StopSign

