cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10021338 Main Street: BLAKENEY_PRESERVE_DR				Street:	N/A	Location:	SE		
ADA ID: 34BE60CA4447 Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Date			a Compliance Description		Data
		Remove & Replace Entire Ram	D .	N/A	Ramp Length (in)	73.0	Yes	Ramp Slope (%)	6.2
the second secon		·····	1.	No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	4.9
THE	5			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
C. ARUA				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
0 0	1 44 00			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
6	A A A A A A A A A A A A A A A A A A A			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
E C	an the	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E. A.	30	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6. 6	E Start			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second secon	. And the			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
E -	ATT I A			N/A	Shared Landing?	N/A			
	4 K-	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	-1-1	R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	THE LAN			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
molt give					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
The LEISon			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name BLAKENEY PRESERVE DR					X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

