

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10036588Main Street: RUNNYMEDE_LNCross Street: N/ALocation:NWADA ID: 34EEDEE2C36ARamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 13.75

Codes/Mitigation Info/Possible Solution



Street 1 Name ENTRANCE
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:					
Remove & Replace Entire Ramp.					
	•				
	I				
Surveyor Notes:					
N/A					
N/A					
PROW/ADA:	ı				
Not Found, R304.2.2, R304.5.3	ı				
	ı				
	ı				

T.
5

Total Cost:



1850.00

Field Measurements/Component Compliance							
Compliance Description		Data	Comp	oliance Description	Data		
N/	A Ramp Length (in)	72.0	No	Ramp Slope (%)	8.8		
Ye	s Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.4		
N/	A Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/	A Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/	A Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/	A Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/	A Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/	A Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/	A Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/	A Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/	A Shared Landing?	N/A					
N/	A Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/	A Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/	A Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A		
N/	A X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	4.3		X Walk 2 X Slope (%)	N/A		
N/	A Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/	A Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
Alter Visio			Yes	Surface Condition? (G/P)	Good		

