

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 53202 Main Street: FLINTROCK_RD Cross Street: LITTLE_ROCK_RD Location: N

ADA ID: 351A8B5E19A2 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

Codes/Mitigation Info/Possible Solution



Street 1 Name FLINTROCK RD
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

ľ	Possible Solutions:					
100	Remove & Replace Entire Ramp.					
Ź						
d						
CASTON DE	Surveyor Notes:					
	N/A					
N						
Š						
2						
	PROW/ADA:					
	Not Found, R304.5.1, R304.2.2,					
ŝ	R304.5.3					
N						



Total Cost:



1850.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance Description	Data		
N/A	N/A Ramp Length (in)		No	Ramp Slope (%)	9.6		
No	Ramp Width (in)	46.5	No	Ramp XSlope (%)	2.2		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	96.0	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	4.8		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type		l	Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		