cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•			,					
Intersection ID: 18832	Main Street: SENECA_PL			Cross	Cross Street: VALLEY_STREAM_RD				Location:	
ADA ID: 3537B4DBBD78	Ramp Type: PerpDiag			Initial	Initial Pass/Fail: Fail Overall Complianc				o Severity Score:	55
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description		Data	Comp	ance Description	Data
		Remove & Replace Curb R Two New Directional Ramp Equivalent.	Ramn	With	N/A	Ramp Length (in)	72.0	No	Ramp Slope (%)	11.1
CALLAN S			•		No	Ramp Width (in)	34.0	No	Ramp XSlope (%)	14.7
1 1 m					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A PARA					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	APP	Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
SELES SELES					N/A	Landing Length (in)		N/A	DWS Provided?	N/A
	P RAN				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)		N/A	DWS Length (in)	N/A		
	Fail and	N/A			N/A	Landing X Slope (%)	N/A		DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
the a set		PROW/ADA:			N/A	Gutter Ponding?		N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.2.	4 7 7	n	N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
	and the second	R304.5.3	4.2.2	,	N/A	Painted X Walk1?	No		Painted X Walk2?	No
N304.3.3					N/A	X Walk 1 Direction	To N		X Walk 2 Direction	To W
the take 1.				N/A		N/A	N/A	X Walk 2 Width (in)	N/A	
					N/A	X Walk 1 Width (in)		N/A	()	
Street 1 Name	SENECA PL					X Walk 1 Slope (%)	6.0		X Walk 2 Slope (%)	5.3
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	5.5		X Walk 2 X Slope (%)	4.6
Street 2 Name	VALLEY STREAM RD				N/A	Ramp inside XWalk1?	N/A		Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign					Road Slope (%)	6.4	N/A	Clear Space?	N/A
						Road X Slope (%)	0.6		Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

s Surface Condition? (G/P)

Good

