

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13822 Main Street: W_WORTHINGTON_AV Cross Street: WICKFORD_PL Location: E

ADA ID: 35B009BE0695 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 37.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

WICKFORD PL StopSign W WORTHINGTON AV None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.2.2, R304.5.3

Total Cost: \$ 3200.00

| i iola mododi omonto/oomponont oomphanoo | | | | | | |
|--|------------------------|-------|------------------------|-----------------------------|-------|--|
| Compli | Compliance Description | | Compliance Description | | Data | |
| N/A | Ramp Length (in) | 69.0 | No | Ramp Slope (%) | 8.5 | |
| Yes | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 11.0 | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| N/A | Shared Landing? | N/A | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No | |
| | X Walk 1 Direction | To NW | | X Walk 2 Direction | To SW | |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| | X Walk 1 Slope (%) | 0.9 | | X Walk 2 Slope (%) | 1.4 | |
| | X Walk 1 X Slope (%) | 7.8 | | X Walk 2 X Slope (%) | 2.3 | |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| | Road Slope (%) | 3.8 | N/A | Clear Space? | N/A | |
| | Road X Slope (%) | 5.2 | N/A | Clear Space to XWalk (in) | N/A | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | | | | | | |

N/A

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Good







Obstruction Type