

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9283	Main Street: FERNDAL PL	Cross Street: THE PLAZA	Location:	S
ADA ID: 363D68976E76	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 8.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
 Street 1 Name THE PLAZA Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	70.5	Yes	Ramp Slope (%)	7.1
			No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	0.1
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A				
		N/A	Gutter Ponding?	N/A	N/A	N/A	Gutter Slope (%)	N/A
		N/A	Gutter Lip Ht (in)	N/A	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No	N/A	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To W			X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	N/A	X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	3.1			X Walk 2 Slope (%)	N/A
			X Walk 1 X Slope (%)	0.4			X Walk 2 X Slope (%)	N/A
		N/A	Ramp inside XWalk1?	N/A	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	N/A	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	N/A	Storm Grate/Utility Hazard?	N/A
			Obstruction Type				Storm Grate/Utility Type	
				N/A				N/A
						Yes	Surface Condition? (G/P)	Good
Total Cost:		\$ 1850.00						

Total Cost: \$ 1850.00

