


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 8266	Main Street: CATHERINE_SIMMONS_AV	Cross Street: MADRID_ST	Location: NW
ADA ID: 36521BD9FC3A	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 21.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

		Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	42.0	Yes	Ramp Slope (%)	5.5
		Surveyor Notes:		No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	6.3
		N/A		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		PROW/ADA:		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		Not Found, R304.5.1, R304.5.3		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To S		X Walk 2 Direction	To E
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	2.8
					X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)	0.5
				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	4.1	N/A	Clear Space?	N/A
					Road X Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
							N/A		N/A
							Yes	Surface Condition? (G/P)	Good

Total Cost: \$ 3200.00

