cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10041624	CENCERS	esses Street: N/A				Location:	NW				
ADA ID: 3654F950DA51	Ramp Ty	Ramp Type: Combination2Diag In				ail: Fail Overall C	o Severity Score:	0			
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
Bos		Possible Solutions:			Compliance Description		Data Compliance Description		Data		
REFER N		Remove & Replace Cu	rb Ran	np With	N/A	Ramp Length LT (in)	61.5	N/A	Ramp Length RT (in)	N/A	
		Two New Directional R			No	Ramp Width LT (in)	47.0	N/A	Ramp Width RT (in)	N/A	
		Equivalent.			Yes	Ramp Slope LT (%)	6.3	N/A	Ramp Slope RT (%)	N/A	
	- 0				Yes	Ramp XSlope LT (%)	1.1	N/A	Ramp XSlope RT (%)	N/A	
	A deal				N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	12.3	
	A A	4			No	Ramp Width (in)	45.0	Yes	Ramp XSlope (%)	0.8	
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	DR	N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
STUTIVE GENU					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
WILL BISOU					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
MILLIAN &	21				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
i. a	21	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		Not Found, R304.5.1, F R304.2.2	304.5.	.1,	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A N/A	
		N304.2.2			N/A N/A	Shared Landing?	N/A	IVA		19/2	
and the contraction					N/A N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
						-					
Street 1 Name					N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1 ALL EXECUTIVE C					N/A	Painted X Walk1?	No To E	N/A	Painted X Walk2?	No To N	
Street 2 Name	None					X Walk 1 Direction	To E		X Walk 2 Direction	To N	
Stop Condition-Street 2	ENTRANCE					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
I						X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	0.8	
I						X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	2.3	
I		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
I						Road Slope (%)	2.4		Clear Space?	N/A	
						Road X Slope (%)	5.4	N/A	Clear Space to XWalk (in)	N/A	
Contraction of the second s			and a	As and	S BOARD			N/A	Any Obstruction?	N/A	
		A CARLEN DE		is all	in bread	· 推动的 - []			Obstruction Type		
			-							N/A	
				man in the		N. Contraction		N/A	Storm Grate/Utility Hazard?	N/A	
		Constanting for a los							Storm Grate/Utility Type		
										NI/A	

N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 13.3





