

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14236 Main Street: LEAKE_ST Cross Street: NOBLES_AV Location: SW

ADA ID: 36D324E6BEA0 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33.75

Codes/Mitigation Info/Possible Solution



Street 1 Name	NOBLES AV
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Fossible Solution	
Possible Solutions:	
Remove & Replace Entire Ramp.	
•	ı
	N
	ı
	ı
	ı
Surveyor Notes:	ı
N/A	ı
	1
	ı
	ı
PROW/ADA:	ı
Not Found, R304.5.1, R304.2.2	ı
	ı
	ı

1		
Total Cost:		\$ 1850.00

Field Measurements/Component Compliance								
Compl	iance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	12.7			
No	Ramp Width (in)	45.0	Yes	Ramp XSlope (%)	0.3			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	6.6		X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			





