

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 20806	Main Street: OLD_REID_RD C				oss Street: PATRICK_PL				Location:	S
ADA ID: 36DC7D8F58CC	Ramp Ty	amp Type: PerpDiag			itial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	22.5
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	12-0-13	Possible Solutions:			Compliance Description		Data Complianc		liance Description	Data
		Remove & Replace Curb Ra	amp	With	N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	10.9
		Two New Directional Ramps Equivalent.	•		No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	3.3
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E Co E					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
B A A A A A A A A A A A A A A A A A A A		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	· max	X			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A				
-63/		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	6 X	Not Found, R304.5.1, R304	.2.2.	)	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		R304.5.3	,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	<u>.</u>				X Walk 1 Direction	To NE		X Walk 2 Direction	To NW	
The second second					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name O	DLD REID RD	-				X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	1.3
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	1.5
Street 2 Name	PATRICK PL				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign					Road Slope (%)	1.8	N/A	Clear Space?	N/A
						Road X Slope (%)	2.5	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A
								Yes	Surface Condition? (G/P)	Good





