


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 24114	Main Street: ARBOR_POINTE_DR	Cross Street: STONEY_CORNER_LN	Location: SW
ADA ID: 36F1BA2225A6	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>	
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>		N/A	Ramp Length (in)	50.0	No
			Yes	Ramp Width (in)	48.0	Yes
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A
			N/A	Shared Landing?	N/A	
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A
			N/A	Painted X Walk1?	No	N/A
				X Walk 1 Direction	To E	
			N/A	X Walk 1 Width (in)	N/A	N/A
				X Walk 1 Slope (%)	0.4	
				X Walk 1 X Slope (%)	0.5	
			N/A	Ramp inside XWalk1?	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.2</p>						
				Road Slope (%)	1.9	N/A
				Road X Slope (%)	0.5	N/A
			N/A	Any Obstructions?	N/A	N/A
				Obstruction Type		
					N/A	N/A
			Yes	Surface Condition? (G/P)	Good	Good

Street 1 Name	STONEY CORNER LN
Stop Condition-Street 2	StopSign
Street 2 Name	ARBOR POINTE DR
Stop Condition-Street 1	None

Total Cost: \$ 3200.00

