

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 28882 Main Street: EDEN HALL CT Cross Street: GEORGIAN HALL DR Location: SW ADA ID: 36FD41DBA751 Ramp Type: Perp Initial Pass/Fail: Pass **Overall Compliance: No Severity Score:** 30

**Codes/Mitigation Info/Possible Solution** 



**GEORGIAN HALL DR** Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions: Remove & Replace Entire Ramp. Remove & Replace Gutter. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2-Perp, R304.3.2-Para, R305, R302.7.2, R304.5.4, R304.5.3

Total Cost: 2600.00

| Field Measurements/Component Compliance |                       |        |      |                             |      |
|---|-----------------------|--------|------|-----------------------------|------|
| Compliance Description                  |                       | Data   | Comp | liance Description          | Data |
| N/A                                     | Ramp Length (in)      | 49.0   | Yes  | Ramp Slope (%)              | 6.6  |
| Yes                                     | Ramp Width (in)       | 50.0   | Yes  | Ramp XSlope (%)             | 1.9  |
| N/A                                     | Flare Type LT         | Sloped | N/A  | Flare Type RT               | N/A  |
| N/A                                     | Flare Slope LT (%)    | 7.9    | Yes  | Flare Slope RT (%)          | 2.5  |
| N/A                                     | Flare Traversable LT? | Yes    | N/A  | Flare Traversable RT?       | Yes  |
| Yes                                     | Landing Length (in)   | 48.0   | No   | DWS Provided?               | No   |
| Yes                                     | Landing Width (in)    | 48.0   | N/A  | DWS Contrast?               | No   |
| No                                      | Landing Slope (%)     | 3.5    | N/A  | DWS Length (in)             | N/A  |
| Yes                                     | Landing X Slope (%)   | 1.2    | N/A  | DWS Full Width?             | No   |
| N/A                                     | Landing Curb? (Y/N)   | No     | N/A  | DWS Offset (in)             | N/A  |
| N/A                                     | Shared Landing?       | No     |      |                             |      |
| Yes                                     | Gutter Ponding?       | No     | No   | Gutter Slope (%)            | 10.6 |
| No                                      | Gutter Lip Ht (in)    | 1.0    | No   | Gutter X Slope (%)          | 2.3  |
| N/A                                     | Painted X Walk1?      | No     | N/A  | Painted X Walk2?            | N/A  |
|   | X Walk 1 Direction    | To E   |      | X Walk 2 Direction          | N/A  |
| N/A                                     | X Walk 1 Width (in)   | N/A    | N/A  | X Walk 2 Width (in)         | N/A  |
|   | X Walk 1 Slope (%)    | 4.8    |      | X Walk 2 Slope (%)          | N/A  |
|   | X Walk 1 X Slope (%)  | 2.2    |      | X Walk 2 X Slope (%)        | N/A  |
| N/A                                     | Ramp inside XWalk1?   | N/A    | N/A  | Ramp inside XWalk2?         | N/A  |
|   | Road Slope (%)        | N/A    | N/A  | Clear Space?                | Yes  |
|   | Road X Slope (%)      | N/A    | N/A  | Clear Space to XWalk (in)   | N/A  |
| Yes                                     | Any Obstructions?     | No     | Yes  | Storm Grate/Utility Hazard? | No   |
|   | Obstruction Type      |        |      | Storm Grate/Utility Type    |      |
|   |                       | N/A    |      |                             | N/A  |
|   |                       |        | Yes  | Surface Condition? (G/P)    | Good |
|   | 20 1 F 18 A           | ,      | •    |                             |      |





