## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10041226	041226 Main Street: WEDGEWOOD_DR				Cross Street: N/A				Location: SW		
ADA ID: 370D392F2DC1	Ramp Type: Combination2				Initial Pass/Fail: Fail Overall Complian				nce: No Severity Score: 25		
Codes	s/Mitigation Info	/Possible Solution	I			Field Measure	ments/C	ompo	nent Compliance		
	Possible Solutions:		Compliance Description			Data Compliance Description			Data		
Carles Harts 1	· · · · · · · · · · · · · · · · · · ·	Remove & Repl	ace Entire Ramp		N/A	Ramp Length LT (in)	62.0	N/A	Ramp Length RT (in)	N/A	
	the second			-	Yes	Ramp Width LT (in)	59.0	N/A	Ramp Width RT (in)	N/A	
	ALANA				No	Ramp Slope LT (%)	10.7	N/A	Ramp Slope RT (%)	N/A	
4					No	Ramp XSlope LT (%)	2.9	N/A	Ramp XSlope RT (%)	N/A	
N Start					N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	3.6	
1 Person 1 Mag	- Frank				Yes	Ramp Width (in)	59.0	No	Ramp XSlope (%)	5.3	
	en la serie	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
the second second	N A A	N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
A A A A A					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	11				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
a sea a stall in the	N W				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N.C.	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
and a second second	And the second second	Not Found, R30	4.5.3. R304.3.2		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
a a support	3 ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) (	,,,,,,,, .	,		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
THE REPORT OF THE PARTY OF					N/A	Shared Landing?	N/A				
A A A A A A A A A A A A A A A A A A A					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	ENTRANCE				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	6.0		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$ 1	600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
		States.		the first star				N/A	Any Obstruction?	N/A	
	TARK I	and the second							Obstruction Type		
				1						N/A	
								N/A	Storm Grate/Utility Hazard?	N/A	
				-		S F			Storm Grate/Utility Type	19/7	
	1 dest		-	-	The					N/A	
	and the second designed the second designed and the se	A REAL PROPERTY AND A REAL	And and a subscription of the subscription of	1							

Yes Surface Condition? (G/P) Good Curb Slope (%) 16.4