cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31882	Main Street: STOWE_DERBY_DR			Street:	CENTERLINE_DR	Location:	SW			
ADA ID: 37147A712BC4	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	35	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
Possible Solutions:		_		Compliance Description		Data Compliance Description		Data		
		Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.	Vith	N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	12.3	
			· · · · ·	No	Ramp Width (in)	41.0	No	Ramp XSlope (%)	5.0	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
and charter				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
5				N/A	Landing Length (in)	N/A		DWS Provided?	N/A	
CENTERLINE 6. C				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	aller 1	K304.3.1, K304.2.2, K304.3.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	A A				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE	
	7 4 To 8 10			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	STOWE DERBY DR				X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	3.5	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.0 1.1		X Walk 2 X Slope (%)	5.9	
Street 2 Name	CENTERLINE DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None			10/4	Road Slope (%)	5.0	N/A	Clear Space?	N/A	
	None				Road X Slope (%)	4.2	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	4.2 N/A		Storm Grate/Utility Hazard?	N/A N/A	
		Total Cost: \$ 3	200.00	11/7	Obstruction Type	17/4		Storm Grate/Utility Type	11/2	
		νται σουτ. ψυ	200.00			N/A		Storm Oraco, Otimey Type	N/A	
						IN/A			IN/A	

Yes Surface Condition? (G/P)

Good

