


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 7308	Main Street: HIDDEN_FOREST_DR	Cross Street: ROSETREE_CT	Location:	W
ADA ID: 373288EE675D	Ramp Type: Combination2	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 1.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	<b>Remove &amp; Replace Entire Ramp.</b>		<b>N/A</b>	Ramp Length LT (in)	<b>55.0</b>
			<b>Yes</b>	Ramp Width LT (in)	<b>48.0</b>
			<b>Yes</b>	Ramp Slope LT (%)	<b>8.3</b>
			<b>No</b>	Ramp XSlope LT (%)	<b>4.2</b>
			<b>N/A</b>	Ramp Length (in)	<b>48.0</b>
			<b>Yes</b>	Ramp Width (in)	<b>48.0</b>
	Surveyor Notes:		<b>N/A</b>	Flare Type LT	<b>N/A</b>
	<b>RT RP &lt; 5%</b>		<b>N/A</b>	Flare Slope LT (%)	<b>N/A</b>
			<b>N/A</b>	Flare Traversable LT?	<b>N/A</b>
<p>PROW/ADA:</p> <p><b>Not Found, R304.5.3</b></p>			<b>N/A</b>	Landing Length (in)	<b>N/A</b>
			<b>N/A</b>	Landing Width (in)	<b>N/A</b>
			<b>N/A</b>	Landing Slope (%)	<b>N/A</b>
			<b>N/A</b>	Landing X Slope (%)	<b>N/A</b>
			<b>N/A</b>	Landing Curb? (Y/N)	<b>N/A</b>
			<b>N/A</b>	Shared Landing?	<b>N/A</b>
			<b>N/A</b>	Gutter Ponding?	<b>N/A</b>
			<b>N/A</b>	Gutter Lip Ht (in)	<b>N/A</b>
			<b>N/A</b>	Painted X Walk1?	<b>No</b>
				X Walk 1 Direction	<b>To SW</b>
<p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p>				X Walk 1 Width (in)	<b>N/A</b>
				X Walk 1 Slope (%)	<b>7.2</b>
				X Walk 1 X Slope (%)	<b>1.2</b>
			<b>N/A</b>	Ramp inside XWalk1?	<b>N/A</b>
				Road Slope (%)	<b>N/A</b>
			<b>N/A</b>	Road X Slope (%)	<b>N/A</b>
				X Walk 2 Direction	<b>N/A</b>
				X Walk 2 Width (in)	<b>N/A</b>
				X Walk 2 Slope (%)	<b>N/A</b>
				X Walk 2 X Slope (%)	<b>N/A</b>
<p>Total Cost:</p> <p><b>\$ 1600.00</b></p>			<b>N/A</b>	Ramp inside XWalk2?	<b>N/A</b>
				Clear Space?	<b>N/A</b>
			<b>N/A</b>	Clear Space to XWalk (in)	<b>N/A</b>
			<b>N/A</b>	Any Obstruction?	<b>N/A</b>
				Obstruction Type	<b>N/A</b>
				Storm Grate/Utility Hazard?	<b>N/A</b>
				Storm Grate/Utility Type	<b>N/A</b>
			<b>Yes</b>	Surface Condition? (G/P)	<b>Good</b>
				Curb Slope (%)	<b>24.6</b>

