cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 10033521 Main Street: OLD_PROVIDENCE_RD | | | | Street: | N/A | Location: | SW | | |
|--|--------------------------|------------------------------|-----------|--|-----------------------|-----------|------|-----------------------------|-------|
| ADA ID: 3734A887539D Ramp Type: PerpDiag | | | Initial F | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 12.5 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | | Possible Solutions: | | Compliance Description Data Con | | | Comp | mpliance Description Data | |
| the state of the second | | Remove & Replace Curb Ramp \ | Nith | N/A | Ramp Length (in) | 60.0 | No | Ramp Slope (%) | 9.1 |
| A STATE AND | | Two New Directional Ramps or | | Yes | Ramp Width (in) | 52.0 | Yes | Ramp XSlope (%) | 2.0 |
| A Dealer and the | | Equivalent. | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | G. A State of the second | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| A STATE OF THE STATE | 8 | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| A PARTY AND | | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | N/A | Shared Landing? | N/A | | | |
| | | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | 1 Mar 1 1 1 1 1 1 | Not Found, R304.2.2 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | All a little ho | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | Eliza Fr | | | | X Walk 1 Direction | To E | | X Walk 2 Direction | To NE |
| make all the same | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | OLD PROVIDENCE RD | | | | X Walk 1 Slope (%) | 1.8 | | X Walk 2 Slope (%) | 2.2 |
| Stop Condition-Street 2 | None | | | | X Walk 1 X Slope (%) | 0.3 | | X Walk 2 X Slope (%) | 3.0 |
| Street 2 Name | ENTRANCE | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | None | | | | Road Slope (%) | 2.8 | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | 1.4 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 3200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |
| 1 | | | | | | | I | | |

Yes Surface Condition? (G/P)

Good

