

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23784 Main Street: E WESTINGHOUSE BV **Cross Street: NATIONS FORD RD** Location: SE **Overall Compliance: No** ADA ID: 379190EE0A89 Ramp Type: PerpDiag Initial Pass/Fail: Fail Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 **E WESTINGHOUSE BV** Signal NATIONS FORD RD Signal

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2

Total Cost: 3200.00 Compliance Description Data Compliance Description Data No N/A Ramp Length (in) 120.0 Ramp Slope (%) 8.6 Yes Ramp XSlope (%) No Ramp Width (in) 45.0 1.3 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A **DWS Provided?** N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? Yes N/A Painted X Walk2? Yes X Walk 1 Direction To NE X Walk 2 Direction To NW N/A 96.0 N/A 97.0 X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) 2.3 X Walk 2 Slope (%) 1.8 X Walk 1 X Slope (%) 1.6 X Walk 2 X Slope (%) 2.4 N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? Yes Yes Road Slope (%) 1.3 N/A Clear Space? N/A N/A Road X Slope (%) 2.2 Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





