

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15403 Main Street: LAWYERS\_RD Cross Street: OLD\_LAWYERS\_RD Location: S

ADA ID: 37A724A27FB8 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

LAWYERS RD None OLD LAWYERS RD StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

| Field Measurements/Component Compliance |                        |                       |       |                        |        |                       |       |
|---|------------------------|-----------------------|-------|------------------------|--------|-----------------------|-------|
|   | Compliance Description |                       | Data  | Compliance Description |        | Description           | Data  |
|   | N/A                    | Ramp Length (in)      | 53.0  | No                     | Ramp   | Slope (%)             | 10.2  |
|   | No                     | Ramp Width (in)       | 46.5  | No                     | Ramp   | XSlope (%)            | 3.2   |
|   | N/A                    | Flare Type LT         | N/A   | N/A                    | Flare  | Type RT               | N/A   |
|   | N/A                    | Flare Slope LT (%)    | N/A   | N/A                    | Flare  | Slope RT (%)          | N/A   |
|   | N/A                    | Flare Traversable LT? | N/A   | N/A                    | Flare  | Traversable RT?       | N/A   |
|   | N/A                    | Landing Length (in)   | N/A   | N/A                    | DWS    | Provided?             | N/A   |
|   | N/A                    | Landing Width (in)    | N/A   | N/A                    | DWS    | Contrast?             | N/A   |
|   | N/A                    | Landing Slope (%)     | N/A   | N/A                    | DWS    | Length (in)           | N/A   |
|   | N/A                    | Landing X Slope (%)   | N/A   | N/A                    | DWS    | Full Width?           | N/A   |
|   | N/A                    | Landing Curb? (Y/N)   | N/A   | N/A                    | DWS    | Offset (in)           | N/A   |
|   | N/A                    | Shared Landing?       | N/A   |                        |        |                       |       |
|   | N/A                    | Gutter Ponding?       | N/A   | N/A                    | Gutte  | r Slope (%)           | N/A   |
|   | N/A                    | Gutter Lip Ht (in)    | N/A   | N/A                    | Gutte  | r X Slope (%)         | N/A   |
|   | N/A                    | Painted X Walk1?      | No    | N/A                    | Painte | ed X Walk2?           | No    |
|   |                        | X Walk 1 Direction    | To NE |                        | X Wa   | lk 2 Direction        | To NW |
|   | N/A                    | X Walk 1 Width (in)   | N/A   | N/A                    | X Wa   | lk 2 Width (in)       | N/A   |
|   |                        | X Walk 1 Slope (%)    | 7.0   |                        | X Wa   | lk 2 Slope (%)        | 0.6   |
|   |                        | X Walk 1 X Slope (%)  | 0.9   |                        | X Wa   | lk 2 X Slope (%)      | 3.6   |
|   | N/A                    | Ramp inside XWalk1?   | N/A   | N/A                    | Ramp   | inside XWalk2?        | N/A   |
|   |                        | Road Slope (%)        | 1.6   | N/A                    | Clear  | Space?                | N/A   |
|   |                        | Road X Slope (%)      | 4.0   | N/A                    | Clear  | Space to XWalk (in)   | N/A   |
|   | N/A                    | Any Obstructions?     | N/A   | N/A                    | Storm  | Grate/Utility Hazard? | N/A   |
|   |                        | Obstruction Type      |       |                        | Storm  | Grate/Utility Type    |       |
|   |                        |                       | N/A   |                        |        |                       | N/A   |
|   |                        |                       |       | Yes                    | Surfa  | ce Condition? (G/P)   | Good  |
|   |                        |                       |       |                        |        |                       |       |





