

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10032566Main Street:N_GRAHAM_STCross Street:N/ALocation:WADA ID: 37CC2895A05BRamp Type:ParaInitial Pass/Fail:PassOverall Compliance:NoSeverity Score:0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name

N GRAHAM ST
Stop Condition-Street 1
Signal
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Total Cost: \$ 1250.00

Compliance Description Data		Compliance Description		Data	
N/A	Ramp Length LT (in)	48.0	N/A	Ramp Length RT (in)	60.0
Yes	Ramp Width LT (in)	69.0	Yes	Ramp Width RT (in)	68.0
Yes	Ramp Slope LT (%)	5.5	Yes	Ramp Slope RT (%)	5.8
Yes	Ramp XSlope LT (%)	0.2	Yes	Ramp XSlope RT (%)	2.0
Yes	Landing Length (in)	69.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	72.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.4	Yes	DWS Length (in)	24.0
No	Landing X Slope (%)	2.1	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	Yes	Yes	DWS Offset (in)	0.0
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.7
Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.3
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	109.0	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A
Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			Compliatմurb Slope (%)		1.5





