

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25775Main Street: CARMEL_RDCross Street: PINEVILLE-MATTHEWS_RDLocation:NEADA ID: 37F26DB382ECRamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 21.25

Codes/Mitigation Info/Possible Solution



Street 1 Name PINEVILLE-MATTHEWS RD
Stop Condition-Street 2 YieldSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:	14					
Remove & Replace Entire Ramp.						
	I					
Surveyor Notes:						
N/A						
PDOW/ADA						
PROW/ADA:						
Not Found, R304.5.1, R304.2.2						





Total Cost:



1850.00

Field Measurements/Component Compliance							
Compliance Description Data		Comp	liance Description	Data			
N/A	Ramp Length (in)	59.0	No	Ramp Slope (%)	11.5		
No	Ramp Width (in)	36.0	Yes	Ramp XSlope (%)	0.7		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	124.0	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		