cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13302	Main Sti	Main Street: E_4TH_ST			reet:	E_JOHN_BELK_RA	Location:	W			
ADA ID: 37F6F4A07116	Ramp T	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description				Data Compliance Description Data			
		Remove & Replace I	Entiro Ramn		N/A	Ramp Length (in)	44.0	No	Ramp Slope (%)	8.7	
		Remove & Replace			Yes	Ramp Width (in)	92.0	No	Ramp XSlope (%)	5.4	
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	2 × 11 100	5			N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	S S				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
T B B		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
Anna and an					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
A Star 31 19	RANK				N/A	Shared Landing?	N/A		2		
The second of the	1 Star	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Cotta Co	Not Found, R304.2.2	D30453		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	a phating and	Not i ounu, K304.2.2	, 1304.3.3		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
	and the second					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
					N/A	X Walk 1 Width (in)	110.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	E JOHN BELK RA					X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				10/4	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	1/2					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	¢	1850.00		Obstruction Type	17/4		Storm Grate/Utility Type	19/2	
		10101 0001.	Ψ	1000.00			N/A		Stand Orace Ounty Type	N/A	
							IN/A	1		IN/A	

Yes Surface Condition? (G/P)

Good

