cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 22075	section ID: 22075 Main Street: MAPLERIDGE_DR		Cross Street: THORNCLIFF_DR				Location:	NE
ADA ID: 380A4DAF5D8D Ramp Type: BlendTrans2		Initial P	nitial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	0
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description		Data Compliance Description		Data	
	Remove & Replace Curb Rar	np With	N/A	Ramp Length (in)	51.0	Yes	BlendTrans Slope (%)	3.3
	Two New Directional Ramps		Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	1.8
	Equivalent.		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
			N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
	Surveyor Notes:		N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
	ASP LIP 2.5		N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.5
	6		N/A	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes
E BOR			N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	3.5
the second secon			N/A	Shared Landing?	No			
	PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.5
ATTA - I MALA	Not Found, R305.2		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.2
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To W		X Walk 2 Direction	To S
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name THORN	NCLIFF DR			X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	0.7
Stop Condition-Street 1	None			X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	2.8
Street 2 Name MAPLE	ERIDGE DR		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign			Road Slope (%)	1.3		Clear Space?	Yes
				Road X Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

10.4