

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16335	Main Str	Main Street: SLOAN_ST			STAMEY_CR	Location:	N		
ADA ID: 386E8264A2B8		Ramp Type: Directional1					1.25		
									1.20
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
CONTRACTOR OF	AD Y YA	Possible Solutions:	Compliance Description			Data Compliance Description			Data
	7.05	Remove & Replace Entire Ramp	•	N/A	Ramp Length (in)		N/A	Grade Break?	N/A
	· · · · · ·			Yes	Ramp Width (in)		N/A	Grade Break Slope (%)	0.0
	Cart a			Yes	Ramp Slope (%)		N/A	Grade Break XSlope (%)	0.0
	5 B			No	Ramp XSlope (%)	3.5			
	A CONTRACTOR			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	A	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the second secon	B.	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
ALL ALL	AL KO			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
Ster (and the			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	Stand St. 14	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	No. A - CAL			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	No color			N/A	Painted X Walk1?	No		Road Slope (%)	4.5
Street 1 Name	STAMEY CR				X Walk 1 Direction	To SW		Road X Slope (%)	0.9
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	4.5	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.9	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	23.0

