cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29957	Main Street: PANOS_DR			Street:	SMITH_CORNERS_B	Location:	NE		
ADA ID: 38D5E49C7BC1	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Da			ta Compliance Description		Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	72.0	Yes	Ramp Slope (%)	6.4
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.2
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	and the state of the second state of the			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
The second of th		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
<u> </u>		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
SMITL COR	NERS_BV			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
SUBBLE	and the second second			N/A	Shared Landing?	N/A		DWS Onset (III)	17/2
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
La Contraction of the second					9		N/A		
		R304.5.3		N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
	W Kabal			N/A	Painted X Walk1?	No - w	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To W		X Walk 2 Direction	To S
		1		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PANOS DR				X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	1.9
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	0.4
Street 2 Name	SMITH CORNERS BV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	4.6	N/A	Clear Space?	N/A
					Road X Slope (%)	1.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

