

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6007	Main Str	Main Street: FERRELL_AV			PEACHTREE_RD	Location:	w		
ADA ID: 393944873F33	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	6	Possible Solutions:		Compliance Description			Data Compliance Description		Data
	· · · · · · / /	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	6.0
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.8
	3. 34 / / / /	f		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
FIERD	31110	4		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
and a state of the	1/1X			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Sandy .	2.1.8			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	S.	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A Start Start Start	MARRA V			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	the second second			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
Contraction of the second s		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	1 A	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	Alth				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
the states and				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	FERRELL AV				X Walk 1 Slope (%)	5.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A



Yes

Surface Condition? (G/P)

Good