## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10028484 Main Street: HILLSIDE_AV Cross Street: N/A						Location:	S	
ADA ID: 39A2151A8051 Ramp Type: Perp		Initial Pas	nitial Pass/Fail: Pass Overall Compliance: No			o Severity Score:	15	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	<u>c</u>	Compliance Description		Data Compliance Description		Data	
A LAND AND	Remove & Replace Entire Ram	р. N	A Ramp Leng	th (in) 88.0	Yes	Ramp Slope (%)	6.5	
	Remove & Replace Gutter.	Ye	es Ramp Width	n (in) <b>48.0</b>	Yes	Ramp XSlope (%)	1.1	
the second states and the	and the second se	N	A Flare Type I	LT Sloped	N/A	Flare Type RT	N/A	
and the second second	and the	N	A Flare Slope	LT (%) 8.0	Yes	Flare Slope RT (%)	3.9	
CITULSTOR AV		N	A Flare Trave	rsable LT? Yes	N/A	Flare Traversable RT?	Yes	
		N	o Landing Ler	ngth (in) N/A	Yes	DWS Provided?	Yes	
	Surveyor Notes:	N	b Landing Wide	dth (in) N/A	Yes	DWS Contrast?	Yes	
	N/A	N	<b>o</b> Landing Slo	pe (%) N/A	Yes	DWS Length (in)	25.0	
		N	<b>o</b> Landing X S	Blope (%) N/A	Yes	DWS Full Width?	Yes	
		N	A Landing Cu	rb? (Y/N) No	No	DWS Offset (in)	2.5	
		N	A Shared Lan	ding? No				
Marks of The State	PROW/ADA:	Ye	es Gutter Pond	ding? No	No	Gutter Slope (%)	6.2	
A THE AND AND A POINT	R304.2.1, R304.2.2-Perp, R304.	3.2- Ye	es Gutter Lip H	łt (in) 0.0	Yes	Gutter X Slope (%)	0.5	
	Para, R304.5.3, R305.2, R304.5.	4 N	A Painted X W	Valk1? No	N/A	Painted X Walk2?	N/A	
A CONTRACTOR	F Land		X Walk 1 Di	rection To N		X Walk 2 Direction	N/A	
		N	A X Walk 1 W	idth (in) N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name HILLSI	DE AV		X Walk 1 Slo	ope (%) 3.6		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None		X Walk 1 X	Slope (%) 1.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A	N	A Ramp inside	e XWalk1? N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A		Road Slope	(%) N/A	N/A	Clear Space?	Yes	
			Road X Slop	pe (%) N/A	N/A	Clear Space to XWalk (in)	N/A	
		Y	Any Obstruc	ctions? No	Yes	Storm Grate/Utility Hazard?	No	
	Total Cost: \$	2600.00	Obstruction	Туре		Storm Grate/Utility Type		
				N/A			N/A	

Yes Surface Condition? (G/P)

Good

