




# Access Compliance Report Public Rights-of-Way (Curb Ramps)



|                                         |                        |                                         |                        |
|-----------------------------------------|------------------------|-----------------------------------------|------------------------|
| Intersection ID: 43138                  | Main Street: ASBURY_AV | Cross Street: ATANDO_AV                 | Location: SW           |
| ADA ID: 39D41E57702C                    | Ramp Type: NoRamp      | Initial Pass/Fail: NoRamp               | Overall Compliance: No |
| Severity Score: 100                     |                        |                                         |                        |
| Codes/Mitigation Info/Possible Solution |                        | Field Measurements/Component Compliance |                        |



Possible Solutions:

**Provide Curb Ramp Remove & Replace Entire Ramp.**

Surveyor Notes:

**N/A**

PROW/ADA:

**N/A**

| Compliance | Description | Data |
|------------|-------------|------|
|------------|-------------|------|

Total Cost: \$ 1500.00

