cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18661 Main S	Main Street: HEDGEMORE_DR		Street:	MOCKINGBIRD_LN	Location:	NE		
DA ID: 39FCEC2915BC Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
LA L	Possible Solutions:		Compliance Description			Data Compliance Description		Data
	Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent.	/ith	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	11.4
			Yes	Ramp Width (in)	63.0	No	Ramp XSlope (%)	2.4
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	······		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To W		X Walk 2 Direction	To S
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name HEDGEMORE DR				X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	1.4
Stop Condition-Street 2 None				X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	3.1
Street 2 Name MOCKINGBIRD LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 StopSigr				Road Slope (%)	2.7	N/A	Clear Space?	N/A
				Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good

