

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12640Main Street: W\_MOREHEAD\_STCross Street: WILKINSON\_BVLocation:NEADA ID: 3A1F0ECB0D87Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 26.25

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name	WILKINSON BV
Stop Condition-Street 2	YieldSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Fotal Cost:	\$ 1850.00

Field Measurements/Component Compilance							
Comp	liance Description	Data	Comp	oliance Description	Data		
N/A	Ramp Length (in)	37.0	No	Ramp Slope (%)	14.1		
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.3		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	113.0	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
-							





