


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|-----------------------|------------------------|-------------------------|------------------------|
| Intersection ID: 6255 | Main Street: HOOVER_DR | Cross Street: NEVIN_RD | Location: SW |
| ADA ID: 3A254D220E79 | Ramp Type: Perp | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | Severity Score: 1.25 | |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | |
|--|--|--|---|-----------------------------|-------------|
|  | Possible Solutions: | | Compliance | Description | Data |
| | Remove & Replace Entire Ramp. | | Yes | Ramp Length (in) | 73.0 |
| | | | N/A | Ramp Width (in) | 72.0 |
| | | | N/A | Flare Type LT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A |
| | | | N/A | Flare Traversable LT? | N/A |
| | | | N/A | Flare Type RT | N/A |
| | | | N/A | Flare Slope RT (%) | N/A |
| | | | N/A | Flare Traversable RT? | N/A |
| | | | N/A | DWS Provided? | N/A |
| <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.3</p> | | | N/A | DWS Contrast? | N/A |
| | | | N/A | DWS Length (in) | N/A |
| | | | N/A | DWS Full Width? | N/A |
| | | | N/A | DWS Offset (in) | N/A |
| | | | N/A | Shared Landing? | N/A |
| | | | N/A | Gutter Ponding? | N/A |
| | | | N/A | Gutter X Slope (%) | N/A |
| | | | N/A | Painted X Walk1? | No |
| | | | N/A | X Walk 1 Direction | To NE |
| | | | N/A | X Walk 1 Width (in) | N/A |
| <p>Street 1 Name</p> <p>HOOVER DR</p> <p>Stop Condition-Street 2</p> <p>StopSign</p> <p>Street 2 Name</p> <p>N/A</p> <p>Stop Condition-Street 1</p> <p>N/A</p> | | | N/A | X Walk 2 Width (in) | N/A |
| | | | N/A | X Walk 2 Slope (%) | N/A |
| | | | N/A | X Walk 2 X Slope (%) | N/A |
| | | | N/A | Ramp inside XWalk1? | N/A |
| | | | N/A | Ramp inside XWalk2? | N/A |
| | | | N/A | Road Slope (%) | N/A |
| | | | N/A | Road X Slope (%) | N/A |
| | | | N/A | Clear Space? | N/A |
| | | | N/A | Clear Space to XWalk (in) | N/A |
| | | | N/A | Storm Grate/Utility Hazard? | N/A |
| <p>Total Cost:</p> <p>\$ 1850.00</p> | | | N/A | Storm Grate/Utility Type | N/A |
| | | | N/A | Obstruction Type | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |

