

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14971 Main Street: PIERCE\_ST Cross Street: SCOTT\_AV Location: N

ADA ID: 3A3EE6D83DC2 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 1.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name PIERCE ST
Stop Condition-Street 1 StopSign
Street 2 Name N/A
Stop Condition-Street 2 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3

Total Cost: \$ 1600.00

Compliance Description Data Compliance Description Data 38.0 N/A N/A Ramp Length (in) Grade Break? N/A 50.0 N/A Yes Ramp Width (in) Grade Break Slope (%) 0.0 N/A Yes Ramp Slope (%) 5.2 Grade Break XSlope (%) 0.0 No Ramp XSlope (%) 4.1 N/A Flare Type LT N/A N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) 0.0 N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A 0.0 N/A **DWS Provided?** Landing Length (in) N/A N/A Landing Width (in) 0.0 N/A **DWS Contrast?** N/A N/A Landing Slope (%) 0.0 N/A DWS Length (in) N/A N/A N/A Landing X Slope (%) 0.0 DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset LT (in) N/A N/A Shared Landing? N/A N/A DWS Offset RT (in) N/A N/A **Gutter Ponding?** 0.0 N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) 0.0 N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Road Slope (%) 10.7 To S X Walk 1 Direction Road X Slope (%) 0.2 X Walk 1 Width (in) N/A Clear Space? N/A 10.7 N/A N/A X Walk 1 Slope (%) Clear Space to XWalk (in) X Walk 1 X Slope (%) 0.2 N/A Storm Grate/Utility Hazard? N/A N/A Ramp inside XWalk1? N/A Storm Grate/Utility Type N/A N/A Any Obstructions? N/A **Obstruction Type** Surface Condition? (G/P) Yes Good N/A N/A Curb Slope (%) 4.7





