


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                                         |                         |                                         |                        |
|-----------------------------------------|-------------------------|-----------------------------------------|------------------------|
| Intersection ID: N/A                    | Main Street: CLANTON_RD | Cross Street: ST_VARDELL_LN             | Location: SW           |
| ADA ID: 3ABC3F5746E4                    | Ramp Type: NoRamp       | Initial Pass/Fail: NoRamp               | Overall Compliance: No |
|                                         |                         | Severity Score: 100                     |                        |
| Codes/Mitigation Info/Possible Solution |                         | Field Measurements/Component Compliance |                        |



Possible Solutions:

**Provide Curb Ramp**

Surveyor Notes:

**N/A**

PROW/ADA:

**N/A**

| Compliance | Description | Data |
|------------|-------------|------|
|------------|-------------|------|

Total Cost: \$ 1500.00

