


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                       |                             |                        |
|------------------------|-----------------------|-----------------------------|------------------------|
| Intersection ID: 44317 | Main Street: E_9TH_ST | Cross Street: N_CALDWELL_ST | Location: W            |
| ADA ID: 3AFA64D2F911   | Ramp Type: Perp       | Initial Pass/Fail: Fail     | Overall Compliance: No |
|                        |                       |                             | Severity Score: 21.25  |

| Codes/Mitigation Info/Possible Solution   |  |  | Field Measurements/Component Compliance |                             |             |
|---|--|--|---|-----------------------------|-------------|
|                       | Possible Solutions:                      |  | <b>Compliance</b>                       | <b>Description</b>          | <b>Data</b> |
|   | <b>Remove &amp; Replace Entire Ramp.</b> |  | <b>No</b>                               | Ramp Length (in)            | 52.0        |
|   |  |  | <b>No</b>                               | Ramp Width (in)             | 47.0        |
|   |  |  | <b>N/A</b>                              | Flare Type LT               | N/A         |
|   |  |  | <b>N/A</b>                              | Flare Slope LT (%)          | N/A         |
|   |  |  | <b>N/A</b>                              | Flare Traversable LT?       | N/A         |
|   |  |  | <b>N/A</b>                              | Landing Length (in)         | N/A         |
|   |  |  | <b>N/A</b>                              | Landing Width (in)          | N/A         |
|   |  |  | <b>N/A</b>                              | Landing Slope (%)           | N/A         |
|   |  |  | <b>N/A</b>                              | Landing X Slope (%)         | N/A         |
| <p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>Not Found, R304.5.1, R304.2.2</b></p> |  |  | <b>N/A</b>                              | Flare Type RT               | N/A         |
|   |  |  | <b>N/A</b>                              | Flare Slope RT (%)          | N/A         |
|   |  |  | <b>N/A</b>                              | Flare Traversable RT?       | N/A         |
|   |  |  | <b>N/A</b>                              | DWS Provided?               | N/A         |
|   |  |  | <b>N/A</b>                              | DWS Contrast?               | N/A         |
|   |  |  | <b>N/A</b>                              | DWS Length (in)             | N/A         |
|   |  |  | <b>N/A</b>                              | DWS Full Width?             | N/A         |
|   |  |  | <b>N/A</b>                              | DWS Offset (in)             | N/A         |
|   |  |  | <b>N/A</b>                              | Gutter Ponding?             | N/A         |
|   |  |  | <b>N/A</b>                              | Gutter Lip Ht (in)          | N/A         |
| <p>Total Cost:</p> <p><b>\$ 1850.00</b></p>   |  |  | <b>Yes</b>                              | Painted X Walk1?            | N/A         |
|   |  |  | <b>To SW</b>                            | X Walk 2 Direction          | N/A         |
|   |  |  | <b>N/A</b>                              | X Walk 2 Width (in)         | N/A         |
|   |  |  | <b>2.3</b>                              | X Walk 2 Slope (%)          | N/A         |
|   |  |  | <b>1.0</b>                              | X Walk 2 X Slope (%)        | N/A         |
|   |  |  | <b>N/A</b>                              | Ramp inside XWalk1?         | N/A         |
|   |  |  | <b>N/A</b>                              | Ramp inside XWalk2?         | N/A         |
|   |  |  | <b>N/A</b>                              | Clear Space?                | N/A         |
|   |  |  | <b>N/A</b>                              | Clear Space to XWalk (in)   | N/A         |
|   |  |  | <b>N/A</b>                              | Storm Grate/Utility Hazard? | N/A         |
| <p>Obstruction Type</p> <p><b>N/A</b></p>   |  |  | <b>N/A</b>                              | Storm Grate/Utility Type    | N/A         |
|   |  |  | <b>N/A</b>                              | Surface Condition? (G/P)    | Good        |

