

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.2

1.6

N/A

No

To N

N/A

0.7

Intersection ID: 10027413 Main Street: GOLF LINKS DR N Cross Street: N/A Location: SW Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5 **ADA ID: 3B6AF40319FE** Ramp Type: PerpDiag

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

Flare Traversable RT?

Data

60.0

48.0

N/A

No

To E

N/A

7.2



Street 1 Name **GOLF LINKS DR N** Stop Condition-Street 2 StopSign **ENTRANCE** Street 2 Name Stop Condition-Street 1 StopSign Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2

Compliance Description N/A Ramp Length (in) Yes Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A

Landing Length (in) Landing Width (in) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) Shared Landing? **Gutter Ponding?** Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%) Road X Slope (%) N/A Any Obstructions? **Obstruction Type**

X Walk 2 Slope (%) 2.6 X Walk 2 X Slope (%) 5.7 N/A N/A Ramp inside XWalk2? N/A 3.9 N/A Clear Space? N/A N/A 5.3 Clear Space to XWalk (in) N/A N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





Total Cost:



3200.00