

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

15.7

0.2

N/A

Good

Intersection ID: 52622 Main Street: HERITAGE POND DR Cross Street: ALEXANDER COMMONS DR Location: Ε 25 ADA ID: 3BA5383578D6 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

95.5

99.5

N/A

Yes

91.5

3.0

1.7

Yes

N/A

N/A

N/A

N/A

To SW



ALEXANDER CROSSING DR Street 1 Name Stop Condition-Street 2 StopSign N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions:
Remove & Replace Entire Ramp.
Surveyor Notes:
N/A
PROW/ADA:
R304.2.2

Total Cost: 1850.00

	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable LT?
	N/A	Landing Length (in)
	N/A	Landing Width (in)
	N/A	Landing Slope (%)
	N/A	Landing X Slope (%)
	N/A	Landing Curb? (Y/N)
	N/A	Shared Landing?
	N/A	Gutter Ponding?
	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%)
	N/A	Ramp inside XWalk1?
		Road Slope (%)
		Road X Slope (%)
	N/A	Any Obstructions?
00		Obstruction Type

N/A

Yes

Compliance Description

Ramp Length (in)

Ramp Width (in)





