


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 5222	Main Street: DOUG_MAYES_PL	Cross Street: GLENWATER_DR	Location:	N/A
ADA ID: 3BD2B2E3B52B	Ramp Type: NoRamp	Initial Pass/Fail: NoRamp	Overall Compliance: No	Severity Score: 100
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance		



Possible Solutions:

**Provide Curb Ramp Remove & Replace Entire Ramp.**

Surveyor Notes:

**N/A**

PROW/ADA:

**N/A**

Compliance	Description	Data
------------	-------------	------

Total Cost: \$ 1500.00

