cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10031809	Main Street: MILLENNIUM_AV			Cross Street: AUDUBON_PARK_DR				Location:	
ADA ID: 3BDD66C2CD3B	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Complia			nce: No Severity Score:		1.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	In 12	Possible Solutions:		Compliance Description			Data Compliance Description		
	15 02 1	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	68.0	N/A	Grade Break?	N/A
				Yes	Ramp Width (in)	72.0	N/A	Grade Break Slope (%)	0.0
				Yes	Ramp Slope (%)	4.2	N/A	Grade Break XSlope (%)	0.0
6.				No	Ramp XSlope (%)	2.4			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1-32			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
6.5 / / S	1 N 19	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the second secon	0	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
E Han				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
		4		N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
J Wer - Charles	211	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	101			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	1 della	•		N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	4		N/A	Painted X Walk1?	No		Road Slope (%)	3.9	
Street 1 Name AUDUBON PARK DR				X Walk 1 Direction	To NW		Road X Slope (%)	1.8	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	3.9	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.8	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	3.9

