

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.8

1.9

N/A

N/A

N/A

Intersection ID: 11259 Main Street: CONNECTICUT AV **Cross Street: SPRINGWAY DR** Location: SE **Overall Compliance: No ADA ID: 3C26ECA4A5F6** Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

Flare Traversable RT?

Data

62.5

43.5

N/A

N/A

N/A

Flare Traversable LT?



Street 1 Name Stop Condition-Street 2 Street 2 Name

Possible Solutions:	Comp	iance	Description
Remove & Replace Entire Ramp.	N/A	Ram	p Length (in)
·	No	Ram	p Width (in)
	N/A	Flare	Type LT
	N/A	Flare	Slope LT (%)
	N/A	Flare	Traversable L
	N/A	Land	ing Length (in)
Surveyor Notes:	N/A	Land	ing Width (in)
N/A	N/A	Land	ing Slope (%)
	N/A	Land	ing X Slope (%
	N/A	Land	ing Curb? (Y/N
	N/A	Share	ed Landing?
PROW/ADA:	N/A	Gutte	er Ponding?
Not Found, R304.5.1, R304.2.2	N/A	Gutte	er Lip Ht (in)
	N/A	Paint	ed X Walk1?
		X Wa	alk 1 Direction
	N/A	X Wa	alk 1 Width (in)
		X Wa	alk 1 Slope (%)
		X Wa	alk 1 X Slope (%
	N/A	Ram	p inside XWalk′
		Roac	Slone (%)

about.	
	A AMERICAN AND A STATE OF THE PARTY OF THE P
100	



