cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10019364	Main Street: AILEEN_CR		Cross Street: N/A				Location: N		
ADA ID: 3D4A79EFE33D	Ramp Ty	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Cor		Complian	ompliance: No Severity Score:		31.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	A HA	Possible Solutions:					ata Compliance Description		Data
C. Mutan	and as	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	51.0	No	Ramp Slope (%)	11.5
		Two New Directional Ramps or	-	No	Ramp Width (in)	34.0	No	Ramp XSlope (%)	2.1
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	231100			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
1. S. C. C. C. C.				N/A	Shared Landing?	N/A			
the start of the	New Y	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
the third of the second s		R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	AL E Ch	,,,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
A LEWS - LA					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	N/A	-			X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	2.5
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	0.3
Street 2 Name	AILEEN CR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.7	N/A	Clear Space?	N/A
					Road X Slope (%)	0.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					•••	N/A		/	N/A

Yes Surface Condition? (G/P)

Good

