

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 10019947 Main Street: ARDREY_KELL_RD			Cross Street: N/A				Location:	W
ADA ID: 3D722DA3C653 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
		Possible Solutions:	Compliance Description Da		iption Data	ta Compliance Description		Data
		Remove & Replace Entire Ramp.	N/A	Ramp Length	n (in) 86.0	No	Ramp Slope (%)	10.3
			Yes	Ramp Width	(in) 58.0	No	Ramp XSlope (%)	3.3
			N/A	Flare Type L	T N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope L	_T (%) N/A	N/A	Flare Slope RT (%)	N/A
		4	N/A	Flare Travers	able LT? N/A	N/A	Flare Traversable RT?	N/A
		c .	N/A	Landing Leng	gth (in) N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:	N/A	Landing Widt	th (in) N/A	N/A	DWS Contrast?	N/A
E.		N/A	N/A	Landing Slop	e (%) N/A	N/A	DWS Length (in)	N/A
I TEL I BUN			N/A	Landing X Sl	ope (%) N/A	N/A	DWS Full Width?	N/A
		-	N/A	Landing Curb	o? (Y/N) N/A	N/A	DWS Offset (in)	N/A
A CARACTER S			N/A	Shared Land	ing? N/A			
		PROW/ADA:	N/A	Gutter Pondi	ng? N/A	N/A	Gutter Slope (%)	N/A
		R304.2.2, R304.5.3	N/A	Gutter Lip Ht	(in) N/A	N/A	Gutter X Slope (%)	N/A
a line a summer of		·	N/A	Painted X Wa	alk1? No	N/A	Painted X Walk2?	N/A
the second se				X Walk 1 Dire	ection To E		X Walk 2 Direction	N/A
6.000			N/A	X Walk 1 Wid	Ith (in) N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ARDREY KELL RD			X Walk 1 Slo	pe (%) 1.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None			X Walk 1 X S	lope (%) 0.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ramp inside	XWalk1? N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road Slope (%) N/A	N/A	Clear Space?	N/A
				Road X Slope	e (%) N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruct	ions? N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00	Obstruction 1	Гуре		Storm Grate/Utility Type	
					N/A			N/A

