

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.6

4.0

N/A

10.7

Yes

No

No

N/A

No

N/A

0.3

3.4

No

To W

N/A

5.4

1.7

N/A

Yes

Intersection ID: 10041619 Main Street: WHITEHALL COMMONS CENTEROSDIStreet: N/A Location: SE

Overall Compliance: No ADA ID: 3DB2F62AC332 Ramp Type: PerpDiag Initial Pass/Fail: Pass Severity Score: 12.75

Codes/Mitigation Info/Possible Solution

None

Field Measurements/Component Compliance

Yes

No

N/A

No

N/A

No

N/A

N/A

N/A

N/A

Yes

No

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

Data

45.0

48.0

2.4

Yes

52.0

48.0

3.8

4.6

No

No

No

0.0

No

To N

Sloped



HALL COMMONS CENTER DR Street 1 Name Stop Condition-Street 2 Street 2 Name **ENTRANCE** Stop Condition-Street 1 StopSign Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3, R304.2.2-Perp, R304.3.2-Para, R304.2.3, R305

	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable LT?
	Yes	Landing Length (in)
	Yes	Landing Width (in)
	No	Landing Slope (%)
	No	Landing X Slope (%)
	N/A	Landing Curb? (Y/N)
	N/A	Shared Landing?
	Yes	Gutter Ponding?
1	Yes	Gutter Lip Ht (in)
•	Yes N/A	Gutter Lip Ht (in) Painted X Walk1?
•		. ,
		Painted X Walk1?
	N/A	Painted X Walk1? X Walk 1 Direction
	N/A	Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in)
	N/A	Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%)
	N/A N/A	Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%)
	N/A N/A	Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1?
	N/A N/A	Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%)

N/A

Yes

Compliance Description

Ramp Length (in)

Ramp Width (in)

I/A	X Walk 1 Width (in)	N/A	N/A
	X Walk 1 Slope (%)	7.5	
	X Walk 1 X Slope (%)	1.1	
I/A	Ramp inside XWalk1?	N/A	N/A
	Road Slope (%)	3.4	N/A
	Road X Slope (%)	1.0	N/A
⁄es	Any Obstructions?	No	Yes
	Obstruction Type		
		N/A	

N/A	Clear Space to XWalk (in)	N/A
Yes	Storm Grate/Utility Hazard?	No
	Storm Grate/Utility Type	
		N/A
Yes	Surface Condition? (G/P)	Good





Total Cost:



3950.00