

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: WILKINSON_BV Cross Street: N/A Location: SE

ADA ID: 3E587D6533CC Ramp Type: Directional2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



The second secon	The state of the s
Street 1 Name	ENTRANCE
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Remove & Replace Entire Ramp. N/A Yes No No No N/A N/A Surveyor Notes: N/A N/A N/A N/A PROW/ADA: R304.2.2, R304.5.3	Possible Solutions:	Com
Yes No No No No N/A Surveyor Notes: N/A N/A N/A N/A PROW/ADA: R304.2.2, R304.5.3 N/A N/A N/A N/A N/A N/A	Remove & Replace Entire Ramp.	N/A
No No N/A N/A Surveyor Notes: N/A N/A N/A N/A N/A PROW/ADA: N/A R304.2.2, R304.5.3 N/A N/A N/A		Yes
N/A N/A Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A R304.2.2, R304.5.3 N/A N/A		No
N/A Surveyor Notes: N/A N/A N/A N/A N/A PROW/ADA: N/A R304.2.2, R304.5.3 N/A N/A		No
Surveyor Notes: N/A N/A N/A N/A N/A N/A N/A PROW/ADA: N/A R304.2.2, R304.5.3 N/A N/A		N/A
N/A N/A N/A N/A N/A N/A N/A PROW/ADA: N/A R304.2.2, R304.5.3 N/A N/A		N/A
N/A N/A N/A N/A PROW/ADA: N/A R304.2.2, R304.5.3 N/A N/A	Surveyor Notes:	N/A
N/A N/A N/A PROW/ADA: N/A R304.2.2, R304.5.3 N/A N/A	N/A	N/A
N/A PROW/ADA: N/A R304.2.2, R304.5.3 N/A N/A		N/A
PROW/ADA: N/A R304.2.2, R304.5.3 N/A N/A		N/A
R304.2.2, R304.5.3 N/A N/A		N/A
N/A	PROW/ADA:	N/A
N/A	R304.2.2, R304.5.3	N/A
	,	N/A
N/A		N/A
		N/A

Total Cost:		\$ 1800.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	oliance Description	Data		
N/A	Ramp Length (in)	105.0	N/A	Grade Break?	N/A		
Yes	Ramp Width (in)	64.0	N/A	Grade Break Slope (%)	0.0		
No	Ramp Slope (%)	8.7	N/A	Grade Break XSlope (%)	0.0		
No	Ramp XSlope (%)	5.3					
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A		
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No		Road Slope (%)	0.5		
	X Walk 1 Direction	To SW		Road X Slope (%)	11.2		
	X Walk 1 Width (in)	N/A	l	Clear Space?	N/A		
	X Walk 1 Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A		
	X Walk 1 X Slope (%)	11.2	N/A	Storm Grate/Utility Hazard?	N/A		
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type			
N/A	Any Obstructions?	N/A			N/A		
	Obstruction Type		Yes	Surface Condition? (G/P)	Good		
		N/A	N/A	Curb Slope (%)	1.8		





