

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 50605	Main Street: DENBUR_DR			Cross Street: RHODORA_RD			Location:	SW	
ADA ID: 3E751883E405	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	10	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:							Data
		Remove & Replace	Entire Ramn	N/A	Ramp Length (in)		Yes	Ramp Slope (%)	6.4
			Linu o Ramp.	No	Ramp Width (in)	42.5	No	Ramp XSlope (%)	4.8
	P. 100			N/A	Flare Type LT		N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
the second se				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
<u>s</u>				N/A	Landing Length (in)		N/A	DWS Provided?	N/A
A P	4.5. C	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E E	Les and a second	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
TOPOLITE C				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Gala	12 · Later			N/A	Landing Curb? (Y/N)		N/A	DWS Offset (in)	N/A
	101 1900			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?		N/A	Gutter Slope (%)	N/A
4 <u>6.</u>	P. 1 1	Not Found, R304.5	1 R304 5 3	N/A	Gutter Lip Ht (in)		N/A	Gutter X Slope (%)	N/A
	2mg 4 1		.1, 1(304.3.3	N/A	Painted X Walk1?		N/A	Painted X Walk2?	N/A
	Carl I				X Walk 1 Direction	To N		X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)		N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	RHODORA RD	•			X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?		N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)		N/A	Clear Space?	N/A
					Road X Slope (%)		N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 11	350.00	Obstruction Type	170		Storm Grate/Utility Type	1975
			Ψ I			N/A			N/A
									100

Yes Surface Condition? (G/P)

Good





