

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4999 Main Street: E_MALLARD_CREEK_CHURCHCROS Street: STONE_QUARRY_RD Location: W

ADA ID: 3E83A3D0A999 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

Codes/Mitigation Info/Possible Solution



1.11.42	Market Samuel Experts
Street 1 Name	MALLARD CREEK CHURCH RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	c	
Remove & Replace Entire Ramp.		
·	N	
	N	
	N.	
	N	
	N	
Surveyor Notes:	N	
N/A	N	
	N	
	N	
	N	
PROW/ADA:	N	
R304.5.1, R304.2.2	N.	
	N	
	N	
	N	

Total Cost:	\$ 1850.00	

Field Measurements/Component Compliance							
Com	oliance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	69.0	No	Ramp Slope (%)	10.1		
No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	2.2		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	7.6		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
A LAND							





