


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 11892	Main Street: BOYER_ST	Cross Street: TAGGART_CREEK_RD	Location: NE
ADA ID: 3EBA8483E241	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance													
	Possible Solutions:		Compliance			Description			Data	Compliance			Description			Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)			60.0			No	Ramp Slope (%)			9.2		
			Yes	Ramp Width (in)			48.0			No	Ramp XSlope (%)			3.0		
			N/A	Flare Type LT			N/A			N/A	Flare Type RT			N/A		
			N/A	Flare Slope LT (%)			N/A			N/A	Flare Slope RT (%)			N/A		
			N/A	Flare Traversable LT?			N/A			N/A	Flare Traversable RT?			N/A		
			N/A	Landing Length (in)			N/A			N/A	DWS Provided?			N/A		
			N/A	Landing Width (in)			N/A			N/A	DWS Contrast?			N/A		
			N/A	Landing Slope (%)			N/A			N/A	DWS Length (in)			N/A		
			N/A	Landing X Slope (%)			N/A			N/A	DWS Full Width?			N/A		
Surveyor Notes:		N/A	N/A			N/A			N/A	DWS Offset (in)			N/A			
PROW/ADA:		R304.2.2, R304.5.3	N/A			N/A			N/A	Gutter Ponding?			N/A			
			N/A			N/A			N/A	Gutter Lip Ht (in)			N/A			
			N/A			No			N/A	Painted X Walk2?			N/A			
						To S				X Walk 2 Direction			N/A			
			N/A	X Walk 1 Width (in)			N/A			N/A	X Walk 2 Width (in)			N/A		
						0.1				X Walk 2 Slope (%)			N/A			
						2.5				X Walk 2 X Slope (%)			N/A			
			N/A	Ramp inside XWalk1?			N/A			N/A	Ramp inside XWalk2?			N/A		
						N/A			N/A	Clear Space?			N/A			
						N/A			N/A	Clear Space to XWalk (in)			N/A			
			N/A	Any Obstructions?			N/A			N/A	Storm Grate/Utility Hazard?			N/A		
										Storm Grate/Utility Type						
									N/A				N/A			
									Yes	Surface Condition? (G/P)			Good			

