


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 28322	Main Street: ARDREY_KELL_RD	Cross Street: BEAU_RILEY_RD	Location:	N
ADA ID: 3EF8EFD078C8	Ramp Type: MedianPerp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 13.75

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
 <p>Street 1 Name BEAU RILEY RD</p> <p>Stop Condition-Street 2 None</p> <p>Street 2 Name N/A</p> <p>Stop Condition-Street 1 N/A</p>	Possible Solutions:	Remove & Replace Entire Ramp.			
	Surveyor Notes:	N/A			
	PROW/ADA:	R304.2.2			
	Total Cost:	\$ 1650.00			
			Compliance	Description	Data
			No	Ramp Length (in)	61.0
			Yes	Ramp Width (in)	58.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	Yes
			To NE	X Walk 1 Direction	N/A
			N/A	X Walk 1 Width (in)	53.0
			2.1	X Walk 1 Slope (%)	N/A
			3.3	X Walk 1 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	Yes
			N/A	Road Slope (%)	N/A
			N/A	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
			N/A	Obstruction Type	N/A
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
			Yes	Surface Condition? (G/P)	Good

