

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 13471	Main Street: FORDHAM_RD	Cross Street: WEST_BV	Location: NW
ADA ID: 3F0C4159BEF3	Ramp Type: ParaDiag	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 0	

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Curb Slope and Extend Ramp.**

Surveyor Notes:

**RT RP < 5%**

PROW/ADA:

**Not Found**

Street 1 Name	WEST BV
Stop Condition-Street 1	None
Street 2 Name	FORDHAM RD
Stop Condition-Street 2	StopSign

Total Cost: \$ 2000.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	53.0	N/A	Ramp Length RT (in)	66.0
Yes	Ramp Width LT (in)	54.5	Yes	Ramp Width RT (in)	59.0
Yes	Ramp Slope LT (%)	6.8	Yes	Ramp Slope RT (%)	2.4
Yes	Ramp XSlope LT (%)	0.7	Yes	Ramp XSlope RT (%)	1.3
Yes	Landing Length (in)	60.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	60.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	0.1	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.2	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.2
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.9
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To S		X Walk 2 Direction	To E
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	3.2
	X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	4.9
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	1.5	N/A	Clear Space?	Yes
	Road X Slope (%)	0.6	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			Replace	Curb Slope (%)	9.5

