

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24910 Main Street: ANNERLY_CT **Cross Street: MACANDREW DR** Location: ADA ID: 3F97C5D74C24 Ramp Type: Directional1 Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 33.75

Codes/Mitigation Info/Possible Solution



ANNERLY CT Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: R304.5.1, R304.2.2, R304.5.3

Total Cost: 1600.00

| Field Measurements/Component Compliance | | | | | |
|---|-----------------------|-------|------|-----------------------------|------|
| Compliance Description | | Data | Comp | liance Description | Data |
| N/A | Ramp Length (in) | 69.0 | N/A | Grade Break? | N/A |
| No | Ramp Width (in) | 41.0 | N/A | Grade Break Slope (%) | 0.0 |
| No | Ramp Slope (%) | 9.8 | N/A | Grade Break XSlope (%) | 0.0 |
| No | Ramp XSlope (%) | 5.2 | | | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | 0.0 |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | 0.0 | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | 0.0 | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | 0.0 | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | 0.0 | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset LT (in) | N/A |
| N/A | Shared Landing? | N/A | N/A | DWS Offset RT (in) | N/A |
| N/A | Gutter Ponding? | 0.0 | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | 0.0 | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | | Road Slope (%) | 2.5 |
| | X Walk 1 Direction | To NW | | Road X Slope (%) | 3.0 |
| | X Walk 1 Width (in) | N/A | | Clear Space? | N/A |
| | X Walk 1 Slope (%) | 2.5 | N/A | Clear Space to XWalk (in) | N/A |
| | X Walk 1 X Slope (%) | 3.0 | N/A | Storm Grate/Utility Hazard? | N/A |
| N/A | Ramp inside XWalk1? | N/A | | Storm Grate/Utility Type | |
| N/A | Any Obstructions? | N/A | | | N/A |
| | Obstruction Type | | Yes | Surface Condition? (G/P) | Good |
| | | N/A | N/A | Curb Slope (%) | 0.2 |
| | | | | | |





