cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

9.4

Good

Surface Condition? (G/P)

Curb Slope (%)

Yes

Intersection ID: 10035606 Main Street: REAVENCREST_PARK_DR					Cross Street: N/A				SW	
ADA ID: 3FD0EBEBB	ig In	Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	0			
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
1 1 1 march		Possible Solutions:		Compliance Description		Data Compliance Description			Data	
	a Draw	Remove & Replace	Curb Ramp With	N/A	Ramp Length LT (in)	29.0	N/A	Ramp Length RT (in)	47.0	
		Two New Directional Ram Equivalent.		Yes	Ramp Width LT (in)	48.0	No	Ramp Width RT (in)	38.8	
1 1000	The main and		-	Yes	Ramp Slope LT (%)	1.0	Yes	Ramp Slope RT (%)	7.8	
				No	Ramp XSlope LT (%)	3.7	No	Ramp XSlope RT (%)	2.2	
	E C			N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	5.1	
the the the	No.			Yes	Ramp Width (in)	57.0	No	Ramp XSlope (%)	5.2	
5 () () () () () () () () () (Surveyor Notes:			Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	<u>L</u>	CURB GAP 2.5		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	LEEZ MAR			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	The second second	PROW/ADA:		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
I profile				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	E SI I III X			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	A REAL AND	Not Found, R304.5.1, R304.5.3		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	2 / <u>a</u>			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				Shared Landing?	N/A					
G.				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name None				N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A	
Stop Condition-Street 1	REAVENCREST PARK DR			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Street 2 Name	StopSign				X Walk 1 Direction	To NE		X Walk 2 Direction	To NW	
Stop Condition-Street 2	N/A				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
					X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	1.9	
					X Walk 1 X Slope (%)	4.7		X Walk 2 X Slope (%)	3.1	
		Total Cost:	\$ 3200.0	0 N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
					Road Slope (%)	1.8		Clear Space?	N/A	
					Road X Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A	
	the second s						N/A	Any Obstruction?	N/A	
							Obstruction Type			
								N/A		
				ALL DE LE DE			N/A	Storm Grate/Utility Hazard?	N/A	
								Storm Grate/Utility Type	177	

